Transducers / transmitters for temperature, humidity, atmospheric pressure and CO2 with 4-20mA interface

All following transducers can be read out via the 4-20mA output.

Temperature Transducer / Transmitter with 4-20mA output

Transducer for:	Transducer for	Transducer for:
Temperature	Humidity	Temperature and humidity
		
Transducer for Temperature	**Transducer for humidity**	**Transducer for Temperature and humidity**
Transducer P0102 (internalr Sensor)	Transducer T1110 (internalr Sensor)	Transducer P3110E (int. Sens.)
Transducer P0122 (internalr Sensor)		Transducer T3110 (int. Sens.)
Transducer P0132 (internalr Sensor)		Transducer T3110Ex (int. Sens.)
Transducer P4101 (ext. Pt1000 Sens.)		Transducer T3111 (ext. Sens.)
Transducer P4121 (ext. Pt1000 Sens.)		Transducer T3111Ex (ext. Sens.)
Transducer P4131 (ext. Pt1000 Sens.)		Transducer T3111P (ext. Sens.)
		Transducer T3113 (int. Sens.)
		Transducer T3113D (int. Sens.)
Transducer P4141 (ext. Pt1000		

Sens.)

Transducer P4151(ext. Pt1000 Sens.)

Transducer P4161 (ext. Pt1000 Sens.)

Transducer P4171 (ext. Pt1000 Sens.)

Transducer P4191(ext. Pt1000 Sens.)

Transducer P6181 (ext. Pt1000 Sens.)

Transducer P6191 (ext. Pt1000 Sens.)

Transducer P0120 (int. Sensor)

Transducer T0110 (int. Sensor)

Transducer T0118 (int. Sensor)

Transducer T4111 (int. Sensor)

Transducer T3113Ex (int. Sens.)

Transducer T3117 (int. Sens.)

Transducer T3118 (int. Sens.)

Complete Catalog 4-20mA/0-10V converter

Complete Catalog 4-20mA/0-10V converter

Complete Catalog 4-20mA/0-10V converter

Transducer for

atmospheric pressure

Transducer for

CO2 concentration

Transducer for

Temperature and CO2







Transducer for Luftdruck	**Transducer for CO2 concentration**	**Transducer for Temperature/CO2**
Transducer T2114 (int. Sens.) Transducer T2118 (int. Sens.)	Transducer T5140 (externer Sensor) Transducer T5141 (int. Sensor) Transducer T5145 (int. Sensor)	Transducer T8148 (internal Sensoren)
Complete Catalog 4-20mA/0-10V converter	Complete Catalog 4-20mA/0-10V converter	Complete Catalog 4-20mA/0-10V converter

Opening the Download-Files May require the Adobe-Acrobat-Reader.
Click here to download the Adobe-Acrobat-Reader.

If you have questions please don't hesitate to contact us any time.

Phone +49 (89) 3133007, **Fax** +49 (89) 3146706, wuntronic@wuntronic.de or send us our Contact form

Wuntronic GmbH, Heppstrasse 30, D-80995 Munich, Germany